San Francisco-Oakland Bay Bridge East Span Seismic Safety Project

SKYWAY INFORMATION HANDOUT

Master CD Index

Skyway Contract No. 04-012024 04-SF-80-13.9-14.3 ALA-80-0.0-1.6

If you have any questions please contact:

The Toll Bridge Program Duty Senior District 04 Office 111 Grand Avenue Oakland CA 94612 Telephone Number: (510) 286-5549

e-mail address duty_senior_tollbridge_district04@dot.ca.gov

Master CD Index

_~	C INIUSCE CD HIUCA			
C				
D				
N		File		
	File Name			
0		Size	Description	
•			_	
	ar405eng.exe	5.49MB	Acrobat Reader	
	readme.txt	175Bytes	Read Me First	
	cd1index.pdf	458KB	CD1 Index	
	curniuex.pui	436KD	San Francisco-Oakland Bay Bridge	
	asbuilt folder	255MB	East Span As-Built Drawings (See	
	asbuilt folder	233WID	pages 9 & 10 for Content of CD1 As-	
			Built Folder) prepared for T.Y. Lin	
			International/Moffat & Nichol Engineers	
			A Joint Venture, prepared by Dokken	
			Engineering	
			<u> </u>	
			(CSWPPP) Conceptual Storm Water	
	cswppp.pdf	1.69MB	Pollution Prevention Plan, dated	
			August 2000 by Caltrans Environmental	
			Engineering Branch	
			Archaeological Survey Reports:	
			Phase 1 Archaeological Survey	
			Report-Maritime Archaeology	
_			(SFOBB) San Francisco-Oakland Bay	
1	1 1 10	9.61MB	Bridge East Span Pile Installation	
	archaeo1.pdf	9.01MB	Demonstration Project, dated	
			September 1999, prepared by James M.	
			Allan of William Self Associates,	
			Reviewed by Michael W. Davis of	
			Parsons Brinckerhoff Inc. & Approved	
			by Mara Melandry for Steven Hulsebus	
			of Caltrans District 4	
			Addondum Archeoological Commun	
			Addendum Archaeological Survey	
			Report-Maritime Archaeology,	
	archaeo2.pdf	877KB	Memorandum Report dated December 6,	
		0//KD	1999, by James M. Allan of William Self Associates, prepared for Mara	
			Melandry & Janet Pape of Caltrans	
			inclanding & Janet Fape of Calitans	
			Addendum Archaeological Survey	
		12.6MB	Report-Maritime Archaeology, dated	
	archaeo3.pdf		March 2000, prepared by James M.	
	a.c.iacos.pai	12.0111	Allan of William Self Associates,	
			Reviewed by Michael W. Davis of	
			Parsons Brinckerhoff Inc. & Approved	
			by Mara Melandry for Steven Hulsebus	
			of Caltrans District 4	
	01 04144110 2 154140 1			
	CD1 CONTINUED NEXT PAGE			
<u> </u>	CDI CONTINUED NEAT FAGE			

	CD1 CONTINUED			
C D N o	File Name	File Size	Description	
1	archaeo4.pdf	1.04MB	Addendum Archaeological Survey Report-Maritime Archaeology, Memorandum Report dated August 17, 2000,by James M. Allan of William Self Associates prepared for Janet Pape of Caltrans	
	debris.pdf	458KB	(SFOBB) San Francisco-Oakland Bay Bridge East Span Underwater Debris Diagram, dated May 2001 (Note: Debris Location is based on "Phase1 Archaeological Survey Report-Maritime Archaeology" and "Addendums Archaeological Survey Report-Maritime Archaeology"	
	survey1.pdf	49.8KB	San Francisco-Oakland Bay Bridge East Span Survey Information: Control Diagram, dated April 25, 2001, provided by Caltrans Survey Branch	
	survey2.pdf	7.25MB	Oakland Mole Survey Information volume 1 of 2: Summary of Photo Control Points and Survey Notes, date of Survey was January 15, 1997 & April 1997, provided by Caltrans Survey Branch	
	survey3.pdf	3.03MB	Oakland Mole Survey Information volume 2 of 2:Control Points on Aerial Photos, date of Survey was January 15,1997 & April 1997, provided by Caltrans Survey Branch	
	uscgform.pdf	192KB	US Coast Guard Private Aids to Navigation Sample Application Form	

CONTENT OF CD 1 AS-BUILT FOLDER					
Bent E23 to E39 Retrofit (Contract No. 04-043431)					
Bent E4-Reconstruction of Top Struts (Contract No. 04-37)					
Cable Realign Sta. 301+86 to Toll Plaza (Cont. 52-15TC1)					
Camera Installation (Contract No. 04-030844)					
Cant. Struct. L. Chord Damage Repair (Cont. 04-035104)					
Deck Drainage Improvements-YBI (Cont. 04-0426404)					
E. Bay L. Deck Truss Scaffold for 288' Span (Cont. 60-15BBC1)					
E. Bay Travel Scaffold Rail Improvements (Cont. 04-029404)					
E. Bay U. Deck Trav. Track Spans YB1- E1 (Cont. 51-15TC2)					
Earthquake Repairs - Pier E18 - E22 (Contract No. 04-190054)					
Earthquake Repairs - Pier E9 (Contract No. 04-190014)					
Earthquake Restrainers (Contract No. C-64158)					
East Bay 288' Span Truss Web Scaffold (Cont. 04-026704)					
East Bay Fenders (Contract No. 04-0474)					
East Bay Ladders and Walkways (Contract No. 04-025504)					
East Bay Lower Deck Travelers (Contract No. 62-15BBC2)					
Electrical Alterations (Contract No. 04-44122)					
Expansion Grating Shields (Contract No. C-54066)					
Fender Repairs W5,E4 and E5 (Contract No. 65-15U38C2)					
Glare Screen (Contract No. 04-64128)					
Int. Seis. Retr. E. Bay Truss Spans E17-E22 (Cont. 04-3004)					
Int. Seis. Retr. E. Bay Truss Spans E9-E16 (Cont. 04-3004)					
Int. Seis. Retr. East Bay 288' Truss YBI (Cont. 04-043004)					
Int. Seis. Retr. East Bay Cant. Truss (Cont. 04-043004)					
Interim Seis. Retr. East Bay 504 Trusses (Cont. 04-043004)					
Interim Seis. Retr. East Bay YBI Viaduct (Cont. 04-043004)					
Interim Seismic Retrofit Roadway Plans (Cont. 04-043004)					
Lower Deck Relamping (Contract No. 04-122054)					
Maintenance Roads (Contract No. 004338)					
Maintenance Safety Improvements (Contract No. 04-001644)					
Marine Radar Beacon (Contract No. 004384)					
Mole Air and Water Lines (Contract No. 04-4065)					
Mole Shoreline Restoration & Improvements (Cont. 040056)					
Pier E9 Seismic Retrofit (Contract No. 190024)					
Proposed Fender Repairs (Contract No. 61-14BBC2)					
Reconstr. Exp. Gratings Upper Deck (Contract No. 04-4093)					
Reconstruct Expansion Joints (Contract No. C-64123)					
Reconstruction - Track Removal (Contract No. C-4003)					
Reconstruction Deck Paving - East Bay (Contract No. 04-4011)					
Reconstruction Deck Surfacing (Contract No. 04-4033)					
Reconstruction Lower Deck Lighting (Contract No. 04-4037)					
Reconstruction Lower Deck Surfacing (Contract No. 04-4024) Perconstruction Sealing Upper Deck Joints (Cont. 04-4036)					
Reconstruction Sealing Upper Deck Joints (Cont. 04-4036)					
(Page 1 of 2)					

CONTENT OF CD 1 AS-BUILT FOLDER				
Reconstruction Steel Work - East Bay (Contract No. 04-4030)				
Reconstruction Structure - YBI (Contract No. 04-4029)				
Reconstruction Upper Deck Lighting (Contract No. C4070)				
Repair of Damaged Member U10-L10 (Contract No. 04-20777)				
Resurface Lower Deck Paving & Striping (Cont. 04-025204)				
Resurfacing Upper Deck (Contract No. 04-014504)				
SFOBB Seismic Retrofit (Contract No. 04-01731)				
South Railing Repair - Span E10 (Contract No. 04-04154)				
Substructure - Girder Span on Mole (Contract No. 8)				
Substructure East Bay Crossing (Contract Nos. 04-4, 04-4A)				
Superstructure East Bay Crossing (Contract No. 04-7)				
Traveler Rail Support Revisions-East Bay (Cont. 04-030304)				
Truss & Railing repair Spans W1,E10,E18 (Cont. 04-04139)				
Truss and Railing Repair, Span E11 (Contract No. 04-4168)				
Upper Deck Lighting Stage 1 (Contract No. 04-004053)				
YB1 Slide Repair - Bent 50 (Contract No. C-64152)				
Yerba Buena Crossing (Contract No. 04-5)				
(Page 2 of 2)				

C			
D			
N	File Name	File	
0		Size	Description
•			
	ar405eng.exe readme.txt	5.49MB	Acrobat Reader Read Me First
	cd2index.pdf	175Bytes 448KB	CD2 Index
	pidpcons.pdf	2.10MB	Pile Installation Demonstration Project (PIDP) Construction Report, dated April 2001, prepared by Mark P. Woods, Mark G. Vilcheck, Beau B. Wrightson of Caltrans
	pidpstor.pdf	92.9KB	Pile Installation Demonstration Project (PIDP) Existing Storage Area, dated April 2001
2	steel.pdf	60.4KB	Steel Products Manufacturing and Fabrication Qualification Audit, Forms, dated May 7, 2001
	precast.pdf	53.4KB	Precast/Prestressed Fabrication Qualification Audit, Forms Dated May 7, 2001
	utcert.pdf	21.3KB	Notification of California Department of Transportation Qualification Requirement for Ultrasonic Testing Personnel
	coc.pdf	13.3KB	Sample-Certificate of Compliance Form
	concret1.pdf	86.3KB	Mass Concrete Report dated January 25, 2001 by Ric Maggenti P.E. Materials & Research Engineer of Caltrans
	concret2.pdf	2MB	Appendix to Mass Concrete Report: Mass Concrete Pours at Dublin 580/680 Interchange, dated January 9, 2001 prepared for Ric Maggenti by Danny L. Callaway P.E. Engineering Service Center, Instrumentation Services Branch of Caltrans
	design1.pdf	113KB	Skyway Structures Design Criteria, dated March 1, 2001 prepared by T.Y. Lin International/Moffat & Nichol Engineers A Joint Venture
	design2.pdf	9.74 KB	List of other Design Criteria Materials Testing Information and Designers References

	footing.pdf	1.63MB	Sample-Drawing of Footing
C D			
N o	File Name	File Size	Description
	ar405eng.exe	5.49MB	Acrobat Reader
	readme.txt	175Bytes	Read Me First
	cd3Index.pdf	446KB	CD3 Index
3	geotch01.pdf	18.6MB	Pile Installation Demonstration Project (PIDP) Geotechnical Report: Main Text & Appendices prepared for Caltrans by Fugro-Earth Mechanics A Joint Venture
	geotch02.pdf	15.9MB	Axial Pile Design and Driveability Main Span-East Pier & Skyway Structures: Main Text and Appendices Dated March 2001, prepared for Caltrans by Fugro-Earth Mechanics A Joint Venture
	geotch03.pdf	3.23MB	Analysis and Design Procedures for Pile Foundations Supporting Temporary Towers Skyway Structures: Main Text and Appendices, dated March 2001, prepared for Caltrans by Fugro-Earth Mechanics A Joint Venture
	geotch04.pdf	42.1MB	Lateral Pile Design for Main Span Pier-E2 and Skyway Structures: Main Text and Appendices dated March 2001, prepared for Caltrans by Fugro-Earth Mechanics A Joint Venture
	geotch05.pdf	481MB	Ground Motion Report: Main Text and Appendices dated March 2001, prepared for Caltrans Caltrans by Fugro-Earth Mechanics A Joint Venture

		ı	T
C			
D			
		T7:1 -	
N	File Name	File	
0	The Name	Size	Description
			2 cocription
	ar405eng.exe	5.49MB	Acrobat Reader
	readme.txt	175Bytes	Read Me First
	TeudificitAt	17313465	Treat Me 1 Hst
	cd4Index.pdf	448KB	CD4 Index
	•		Revised Final Oakland Shore
	geotch06.pdf	12.3MB	Approach Geotechnical Site
			Characterization Report: dated March
			2001, prepared for Caltrans by Fugro-
			Earth Mechanics A Joint Venture,
			Volume-1, Main Text
	geotch07.pdf	10.9MB	Volume-2A, Appendices - By-Borings
	geotch08.pdf	15MB	Volume-2B, Appendices - By-Borings
	geotch09.pdf	11.4MB	Volume-3, Appendices - CPT Soundings
	geotch10.pdf	154MB	Volume-4, Preliminary Study of
	geoteni o.pui	13 1111	Approach Fills, Study-Other Reports;
			Lateral Spreading of Fills, Findings-
			Trench and Pit Excavations and
			Geotechnical Testing for the East-Bay
4			Crossing of SFOBB By UC Berkeley
•	geotch11.pdf	68.6MB	Final Marine Geophysical Survey
		08.0011B	Report : dated March 2001, prepared for Caltrans by Fugro-Earth Mechanics A
			Joint Venture
			Volume-1, Main Text and Appendices
	geotch12.pdf	5.41MB	Volume-2, Maps
			Final Marine Geotechnical Site
	geotch13.pdf	43.3MB	Characterization Report:dated March
			2001, prepared for Caltrans by Fugro-
			Earth Mechanics A Joint Venture
	1.1.1.10	4 6 0) (D	Volume-1, Main Text and Illustrations
	geotch14.pdf	16.2MB	Volume-2A, Individual Boring
	geotch15.pdf	19.5MB	Appendices Volume-2B, Individual Boring
	geotem 3.pui	17.51111	Appendices
	geotch16.pdf	12.4MB	Volume-2C, Individual Boring
	1		Appendices
	geotch17.pdf	12.8MB	Volume-2D, Individual Boring
	. 110	450.55	Appendices
	geotch18.pdf	15MB	Volume-2E, Individual Boring
	geotch19.pdf	14.2MB	Appendices Volume-2F, Individual Boring
	geoteri 7.pui	17.4WD	Appendices
	geotch20.pdf	11.4MB	Volume-2G, Individual Boring
			Appendices
	geotch21.pdf	9.59MB	Volume-2H, CPT Data Appendix
		1	

C			
D			
		17.1	
N	File Name	File	
0	The Name	Size	Description
١.		Size.	Description
		221D 4	D. J.M. Elma
	readme.txt	221Bytes	Read Me First
	cd5Index.pdf	443KB	CD5 Index
	. 1.00 10	5.400 AD	Subcontractor Report -Preliminary
	geotch22.pdf	542MB	Geotechnical Site Characterization,
5			dated June 1998 prepared for Caltrans by
3			Fugro-Earth Mechanics A Joint Venture
			Volume-1, Borehole Geophysics &
		155MB	Televiewer Logs
	geotch23.pdf	13311115	Volume-2, Part-1, Seismic Survey-Yerba
		5 40MD	Buena Island & Pressuremeter Testing Acrobat Reader
	ar405eng.exe	5.49MB	
	readme.txt	175Bytes	Read me First
6	cd6Index.pdf	443KB	CD6 Index
	. 1.0.4 16	6621 AD	Subcontractor Report - Preliminary
	geotch24.pdf	663MB	Geotechnical Site Characterization:
			dated June 1998 prepared for Caltrans by
			Fugro-Earth Mechanics A Joint Venture
			Volume-2, Part-2, BIPS Data - Yerba Buena Island
	ar405eng.exe	5.49MB	Acrobat Reader
	readme.txt	175Bytes	Read Me First
	cd7Index.pdf	443KB	CD7 Index
	cu/maex.pai	443KD	Subcontractor Reports-Preliminary
	geotch25.pdf	14MB	Geotechnical Site Characterization:
	geoten25.pui	141111	dated June 1998, prepared for Caltrans by
7			Fugro-Earth Mechanics A Joint Venture
′			Volume-3, Resonant Column and Cyclic
			Direct Simple Shear Test & Dynamic
			Properties of Intact Soil Specimens
	geotch26.pdf	651MB	Volume-4, Laboratory Rock Testing
	8		Program
	ar405eng.exe	5.49MB	Acrobat Reader
	readme.txt	175Bytes	Read Me First
	cd8Index.pdf	444KB	CD8 Index
			Subcontractor Reports - Final
	geotch27.pdf	381MB	Geotechnical Site Characterization:
			dated March 2001, prepared for Caltrans
8			by Fugro-Earth Mechanics A Joint
1			Venture
			Volume-1, Borehole Geophysics &
			Televiewer Logs
	geotch28.pdf	284MB	Volume-2, Laboratory Rock Testing
	0-0		Program
			- 6
	geotch29.pdf	10.4MB	Volume-3, Seascout CPT Soundings
	<u> </u>	l .	, ,